


DIAL INDICATOR

DIN
878



• 5111-0000 Metric Dial Indicator



- Used to measure surface flatness as well as axial runout and also used to check tool set up and squareness



- Limit indicator clips included
- Strictly made in accordance with DIN878



- Jeweled bearings providing the lowest possible bearing friction
- With narrowed range and higher accuracy

Unit:mm

Code	Range	Graduation	Style	A	B	C	D	E	Accuracy	Hysteresis
5111-0000	0-10	0.01	flat back	10.5	φ58	φ8	20.5	φ53.5	0.017	0.003
5111-1005	0-10	0.01	lug back	10.5	φ58	φ8	20.5	φ53.5	0.017	0.003