



- Make quick and accurate outside measurements of different materials.
- Perfect for woodworking, carpentry, metal fabrication, etc
- High hardness and wear resistance
 - With large LCD display for clear and error-free readings
- The gauge is spring loaded and makes point contact at a constant measuring force
 Unit:mm

| Code | Range | Resolution | Accuracy |
|-----------|------------|------------------|-----------|
| 1804-1020 | 0-150/0-6" | 0.1/0.005"/1/64" | 0.2/0.01" |
| 1804-1025 | 0-200/0-8" | 0.1/0.005"/1/64" | 0.3/0.02" |